




VIBRATION ATTENUATORS PADS GUIDELINE FOR RT 30-40-50
DIRECTIVE DE MONTAGE DES SYSTEMES ANTI-VIBRATION POUR RT 30-40-50
RICHTLINIE DER MONTAGE DER SCHWINGUNGSFREIEN SYSTEME FÜR RT 30-40-50
DIRETTIVA D'ASSEMBLAGGIO DEI SISTEMI ANTI-VIBRATION PER RT 30-40-50
DIRECTIVA DE MONTAJE DE LOS SISTEMAS ANTIVIBRACIONES PARA RT 30-40-50




x 6



x 6



x 6



x 6



Fix the anti-vibration studs on the 6 sites of the support of the machine according to suitable positioning (see following table).

Fixez les plots anti-vibrations sur les 6 emplacements des pieds de la machine suivant le positionnement approprié (voir tableau suivant).

Die Schwingungsdämpfer an den 6 Füßen der Maschine befestigen (siehe Positionierung entsprechend nachstehender Tabelle).

Fije los soportes antivibratorios en los 6 puntos de los pies de la máquina según la localización conveniente (véase cuadro siguiente).

Fissate i perni anti-vibrazioni sulle 6 posizioni dei piedi della macchina secondo il posizionamento adeguato (vedere tabella seguente).



REP.	Weight repartion Répartition du poids Verteilung des Gewichts Ripartizione del peso Distribución del peso			models Modèles Modelle Modelli Modelos
	RT 30	RT 40	RT 50	
1	95	103	111	DRD 90-75
2	100	108	117	
3	105	113	122	
4	105	113	122	
5	100	108	117	
6	95	103	111	

